

N62604.AR.001829  
NCBC GULFPORT  
5090.3a

LETTER DISCUSSING SCHEDULE FOR SITE DEMONSTRATION NCBC GULFPORT MS  
5/3/1985  
TYNDALL AIR FORCE BASE



DEPARTMENT OF THE AIR FORCE  
HEADQUARTERS AIR FORCE ENGINEERING AND SERVICES CENTER  
TYNDALL AIR FORCE BASE, FL 32403

MAY 03 1985

*NCBC  
Schedule*

REPLY TO  
ATTN OF: RDVW

SUBJECT: Schedule for Site Demonstrations at the Naval Construction Battalion Center, Gulfport MS

TO: Mr Wayne Mathis  
U.S. Environmental Protection Agency  
Region 4  
Courtland Street  
Atlanta, Georgia

1. The following is a schedule of events in support of the technology demonstrations at NCBC:

20 May 85	Contractors Arrive on Site
21-22 May	IT Corp Equipment Arrives
22-28 May	IT Equipment Setup
28-31 May	Operate IT System on Clean Soil
5 Jun	News Conference and Press Site Visit
6-21 Jun	Process Contaminated Soil with IT Equipment
22-23 Jun	IT Equip Decon
23 Jun	JM Huber System Arrives
25-26 Jun	JM Huber System Processes Contaminated Soil
25-26 Jun	Second Press Visit to Site
26 Jun	Pick-up of Waste for Transport to Rollins, Deer Park, TX
26-27 Jun	Decon Huber Equipment
1 Jul	IT Equipment Shipped to Johnston Island. Demonstrations Completed

2. Should you or anyone else wish to visit the NCBC site during the demonstrations a coordination procedure is required. Please contact Mr Jim Cluff (NCBC) at (601) 865-2485. You will need to provide information on your itinerary, name and social security number, etc. I am also requesting that you contact my home office at (904) 283-2942. I will provide you with my phone number at NCBC as soon as it is available.

3. I appreciate the cooperation you and your agency have provided. I look forward to continuing the spirit of cooperation between our agencies as we attempt to resolve the complex issues of dioxin contamination at Department of Defense sites.

*Terry L. Stoddart*  
TERRY L. STODDART, Capt, USAF, BSC  
Toxic Waste R&D Program Scientist

cc: Mr Don McGraw, Mississippi DNR  
Mr David Lee, Mississippi DNR  
Mr Art Linton, EPA Region 4  
Mr George Harlow, EPA Region 4  
Mr Conrad Kleveno, HQ EPA  
Mr Paul Des Rosier, HQ EPA/ORD  
Mr Harry Williams, EG/G Idaho  
Mr Jim Cluff, NCBC Code 470